

**Engineering Department** 

**CIP Project Number: AP1001** 

Title: Runway Rehab/Repair

**Project Phase: Design** 

% of Phase Completion

	]	De	sig	n			Construction	n
							2011	

Cost for this Phase: \$30,000

**Funding Sources:** Airport Revenues

**Project Manager: Phillip Savko/TxDOT** 

**Contractor: N/A** 

Consultant: KSA

**Project Description:** As identified in the PER (pavement evaluation study AP0802), this project encompasses rehab, cleaning and re-marking of runway, taxiways and all aircraft parking aprons. Rehab may include spall repair, joint and crack sealing, and panel replacement. Will be funded by a 90/10 TxDOT Aviation Grant (with the Airport share being 10% of the total project cost).

**Justification:** Make necessary repairs and preventative maintenance to runway to ensure safety for our customers, and to prolong the life of the runway and airfield pavement.

**Updates: October 2009 –** This project will begin once the PER is completed for Project AP0802 Pavement Evaluation.

**November 2009 –** Awaiting completion of PER.

**December 2009 –** Awaiting completion of PER.

**January 2010 -**PER in progress.

**February 2010** –PER in progress.

**March 2010** – KSA Engineers and TxDOT Aviation are in the process of negotiating scope and fee for Preliminary Engineering Report.

## **SEE MAP BELOW**

